

Annexure- D

BUILDING SAFETY CERTIFICATE

No. 1321

Dated: 27/03/2026

It is certified that the existing building **BAHIRJI VIDYA MANDIR** (name of the building or premises) at Bahirji College Road, Basmat, Hingoli, Maharashtra (address) is having block(s)/ Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	Ground floor + First floor			Nil		

The building is owned/occupied by **BAHIRJI VIDYA MANDIR** have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of _PWD_ on 27/03/26 in the presence of Mrs. Sumi Micheal, Principal, Bahirji Vidya Mandir and that the building/premises is fit for occupancy for running school with effect from 27/03/2026 for a period of 26/03/2027 years in accordance with rule and subject to compliance of the specific conditions as appended (p. 1).

1. As this certificate is being issued based on visual inspection of building by field officers, any distress is observed subsequently needs
2. to be structurally audited immediately.
3. _____

Issued on 27/03/2026 at Hingoli by _____

Signature with Seal: _____

M.S. Deshmukh
Executive Engineer
P.W. Division, Hingoli

Name: M.S. Deshmukh

Designation: Executive Engineer

Name & Address of Department/ Office
P.W. Division Hingoli.

M.S. Deshmukh
Sub-Divisional Engineer
P.W. Sub-Division, Basmat

Sumi Micheal
PRESIDENT
Bahirji Vidya Mandir
Basmath Dist. Hingoli

Sumi Micheal
Principal
Bahirji Vidya Mandir
Basmath Dist. Hingoli